Warranty Vehicle Inquiry

Thu Aug 08 11:31:38 EDT 2013 *CD00119* *CONFIDENTIAL*

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2013 BMW of North America, LLC

Vehicle Data

VIN: WBSEG9328RCD00119
Chassis Number: CD00119
Line Make: 01 - BMW
Model Year: 1994
AG Model Code/Desc: EG93 - 850CSI/2
NA Model Code/Desc: 9480 - 850CSI
Exterior Trim Code: 324 - OXFORD GREEN METALLIC
Interior Color Code: 0498 - BLCK LTH/WHT TRIM
MSRP: $101,500.00

Davis #: N/A
TCU MIN:
Vehicle Production Date: 1994/07
Motor Type: S70
Platform/Engineering Series: E31
Wholesale Center ID/Loc: 10715-01
Wholesale Date: 10/18/1994
Retail Center ID/Loc: 10715-01
Retail Date: 11/25/1994
In-Service Date: 11/25/1994

New Vehicle Warranty Info

No Coverage As Of: 11/25/1998
Expiration Mileage: 50,000

NO OPEN CAMPAIGNS

Option Information

Code	Description	Code	Description
0089	FULL VPC - 850	0939	pioneer CD / price dependancy
0973	850 PHONE	0ZLX	LUXURY PACKAGE

Customer Information

Chassis Number : CD00119

Name (First/Last):

Adderss:

Contract/Service Program Information

Type	Program Code/Desc	Contract Number/Status	Eff Date	Enroll Date	No Coverage As Of	Exp Age (Mth)	Exp Odometer (Miles)	Retail Center	Center Name	Vendor Code Used	Contract Holder (First/Last)
MP	0000000130 - MP 48 MO/050K MLS	0000000 EXPIRED	11/25/1994	11/21/1996	11/25/1998	48	50,000	10715	BEVERLY HILLS BMW, LTD.	MP	

Repair History (Claims)

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
26718	01	82500	01/10/2006	547102	01/04/2006	01/10/2006	N/A	12,424	3112074800	Rubber/hydraulic mount, tension strut/compression strut (inner) leaking
77996	01	158280	01/22/2003	380102	01/08/2003	01/22/2003	N/A	98,058	6312964500	E31 Pop-up headlight not in position
77996	01	63120	00/00/0000	301254	02/24/2000	00/00/0000	N/A	70,394	0017050100	SIB #17-01-98 RECALL 98V-178 RADIATOR CAP RECALL FOR E31, E32, E34 AND E36 MODELS
77996	01	56640	00/00/0000	294418	11/22/1999	00/00/0000	N/A	67,114	52103013WR	SEAT ADJ ACTUAT UNIT-BROKEN
77996	01	55520	00/00/0000	291154	10/21/1999	00/00/0000	N/A	65,197	5412007500	Slide/double slide/glass sunroof (SHD) corroded
77996	01	603700	00/00/0000	0	08/14/1998	00/00/0000	N/A	52,500	11510148SA	(Main) electrical coolant pump leaking
77996	01	540300	00/00/0000	0	05/21/1998	00/00/0000	N/A	49,999	1142003700 17110077MP 34000077MP 85990091MP	Full-flow filter body loose COOLANT CHANGE MAINTENANCE PROGRAM BRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM OIL SERVICE(MP)AFTER THE 1ST
77996	01	397220	00/00/0000	0	10/29/1997	00/00/0000	N/A	43,749	85990093MP	INSPECTION 2 (MP)
77996	01	394490	00/00/0000	0	10/29/1997	00/00/0000	N/A	43,749	6133007900	Horn incorrect connection /contact
77996	01	339270	00/00/0000	0	08/27/1997	00/00/0000	N/A	40,733	3613013700 6575301400	Wheel cap / hub cover loose Burglar alarm system occasional malfunction
77996	01	391210	00/00/0000	0	05/30/1997	00/00/0000	N/A	37,632	0064050100	*LIMITED WARRANTY* SIB #64-08-96 LABEL CODE 186

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2013 BMW of North America, LLC

Chassis Number : CD00119

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
77996	01	291210	00/00/0000	0	05/30/1997	00/00/0000	N/A	37,632	11000077MP 85990093MP	MISCELLANEOUS - MAINTENANCE PLAN INSPECTION 2 (MP)
77996	01	146830	00/00/0000	0	10/29/1996	00/00/0000	N/A	29,592	6581001800	On-board computer (instrument cluster) incorrect/incomplete reading
77996	01	201350	00/00/0000	0	04/24/1996	00/00/0000	N/A	21,224	17110077MP 34000077MP	COOLANT CHANGE MAINTENANCE PROGRAM BRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM
77996	01	200350	00/00/0000	0	04/24/1996	00/00/0000	N/A	21,224	0065012100	Discontinued- take no action.
77996	01	200050	00/00/0000	0	04/24/1996	00/00/0000	N/A	21,224	4100017700 65750012A5	\\\\ NO LOCAL LANG DESCRIPTION FOR THIS DEFECT COD CONTR UNIT-FAILED(BMW/ALPINE)
77996	01	13520	00/00/0000	0	04/24/1996	00/00/0000	N/A	21,224	85990091MP	OIL SERVICE(MP)AFTER THE 1ST
77996	01	3520	00/00/0000	0	04/24/1996	00/00/0000	N/A	21,224	2121005800	Complete clutch slipping
77996	01	723110	00/00/0000	0	11/06/1995	00/00/0000	N/A	15,802	6763034800	Pump, windshield cleaning system leaking
77996	01	715580	00/00/0000	0	10/26/1995	00/00/0000	N/A	14,971	6453024800 85990091MP	Air conditioning condenser leaking OIL SERVICE(MP)AFTER THE 1ST
77996	01	15580	00/00/0000	0	10/26/1995	00/00/0000	N/A	14,971	0012015700	SIB #12-03-95 (4215) REPLACE ELECTRONIC THROTTLE MODULE (EML) E31 850CSI
77996	01	66120	00/00/0000	0	03/31/1995	00/00/0000	N/A	5,700	11120077BV 5116162900 5210031300	UNKNOWN Upper glove box, passengers side sticking/jammed Backrest adjustment, front seat broken
10715	01	582770	00/00/0000	0	02/24/1995	00/00/0000	N/A	5,357	5220156500 7260798500	Backrest latch / rear seat adjustment does not lock into position Reading light not passed
10715	01	536070	00/00/0000	0	11/30/1994	00/00/0000	N/A	12	5116163700	Upper glove box, passengers side loose
66682	01	428090	00/00/0000	0	10/17/1994	00/00/0000	N/A	6	5191315400	Paint finish of front bumper trim panel/body moulding scratches, score marks

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2013 BMW of North America, LLC