

Vehicle Specification

VIN:	WBSHC910X0GD64510	Production Date:	Oct 17, 1994
Model:	HC91 M5	Engineering Series:	E34
Color:	0283 daytona-violett	Motor Type:	S38
Trim:	A9SL Cloth "Hurrican"/silver-grey	Last Odometer Reading:	0 miles

Options

Factory Installed:

0243	Airbag for front passenger
0302	Alarm system
0320	Deleted, model lettering
0339	SATIN CHROME
0354	Green windscreen, green shade band
0415	Sun-blind, rear
0417	Roller sun vizor, rear door
0423	Floor mats, velours
0494	Seat heating driver/passenger
0500	Headlight wipe/wash/Intensive cleaning
0530	Air conditioning
0540	Cruise control
0629	Car telephone (GSM) w card reader, front
0662	BMW BAVARIA C PROFESSIONAL RDS
0672	CD changer for 6 CDs
0676	HiFi speaker system
0686	Antenna-Diversity
0710	M leather steering wheel
0784	AERODYNAMIKSPIEGEL
0900	Electronic immobilizer
0915	Delete clear coat
0944	NACHTRAEGLICHER UMBAU DURCH ZS

Dealer Installed:

Special Equipment:

Code	Description
0944	Z S A L L O C A T E D Bedienhoerer Telefon von Mittelkonsole auf Axicon-Konsole verlegen (Kartenlesegeraet nur noch im Kofferraum)

ECU Configuration:

State of vehicle at date: Dec 6, 2007

Control unit name	Diagnosis date	Hardware No.	Serial No.	Coding Index	Manufacturer
-------------------	----------------	--------------	------------	--------------	--------------

Open Campaigns:

Select	Status	Special defect code	Campaign No.	Label Code	Service Information Bulletin	Description
☐	open	0017060100				E31 E32 E34 E36 Replacement of radiator cap (rest)

Print Date: Dec 6, 2007 11:27 AM